


DORSTENER WIRE TECH

Wire Cloth Vacuum Receiver Disc Filters

Standard flow media with expanded metal support grid.

20 mesh .016"	304ss
40 mesh .010"	304ss
60 mesh .0075"	304ss
80 mesh .0055"	304ss
100 mesh .0045"	304ss
200 mesh .0021"	304ss



Vacuum systems for transporting plastic pellets are found in many polymer processing facilities. Just like any air handling system it's critical that the filters are kept clean and replaced as needed. As pellets are moving through the system they can become hot and soft sometimes leaving a slight plastic skin on the interior walls of the transport pipes. This skin will eventually break loose and develop into streamers or angel hair strands. These strands can clog and destroy filters. If the filters are not replaced the entire system because less efficient and the problem starts to compound. Maintaining and replacing damaged filters is critical to vacuum system performance.



Dorstener Wire Tech
19994 Hickory Twig Way
Spring, TX 77388
Tel: 281-651-6226 Fax 281-651-6228
Web: www.dwt-inc.com
Toll Free: 888-931-9473
Email: sales@dwt-inc.com